

FAAST XS Release Notes

Filename: S04-0172-002

Sensor bootloader version: 1.2

Sensor application version: 1.4

Comms bootloader version: 1.1, 1.2

Comms application version: 1.7

Models affected: All

Description of Changes:

- Fixed time fault errors that may occur during normal operation.

FAAST XS Release Notes

Filename: S04-0172-000

Sensor bootloader version: 1.2

Sensor application version: 1.3

Comms bootloader version: 1.1

Comms application version: 1.5

Models affected: All

Description of Changes:

- User Interface
 - The chamber obscuration was moved from the Home Screen to the **Diagnostics** menu.
 - The **Functions** menu has been re-ordered to provide faster access to the **Reset** function.
- Webservice
 - Added Device information page.
- Modbus
 - Configuration changes are now possible when a device is in CONFIGURATION or DISABLE mode.
 - CLIP devices now support smoke referencing via Modbus.
- General changes
 - Firmware upgrade events are now logged.
 - The default configuration time stamp is 1-Jan-2015.